



Case Study

Supermarket, Gravesend

The bearings on a large backward curved fan collapsed causing the complete failure of the fan, and damaging the flexible connection and AV mounts.

AHS Specialist Services had to cut up the fan in situ to remove it, and provided a new fan in split case format for the replacement due to limited access. New AV mounts, new motor, bushes, pulleys, belts and flexible connection were also installed.

Due to the size of the components a stair walker had to be used to get the components to the plantroom. AHS Specialist Services left the new fan running, and removed all scrap from site within a two day window.

Contact us

Unit 7 Stag Business Park,
164/166 Christchurch Road,
Ringwood, Hampshire,
BH24 3AS

Telephone:
01425 475384

Email:
sales@ahs-ss.uk.com

www.ahs-ss.uk.com

ahs  TM
(Specialist Services) Ltd